Turning Monitors & Super-Touch Screens On/Off

This document serves as a quick reference of how to turn on/off the overhead monitors and SuperTouch consoles in the center.

Turning On Overhead Monitors:

1. From the Conqueror X main menu, click on "Front Desk" then on "All Lanes."
2. Select which lanes you want to turn the monitors on by clicking and dragging.
3. Click on "Special F." on the bottom left of the screen.
4. Click on "TV."
5. The upper left monitor will be selected by default. Click the upper right monitor to select it as well. Both upper monitors should have a yellow border around them indicating they are selected.
6. Click in the drop down under "MMS Service" and select the advertising playlist or service you want to send to the monitors. Click "Send."
7. Click "Close" to close the module.

Turning Off Overhead Monitors:

1. From the Conqueror X main menu, click on "Front Desk" then on "All Lanes."
2. Select which lanes you want to turn the monitors on by clicking and dragging.
3. Click on "Special F." on the bottom left of the screen.
4. Click on "TV".
5. The upper left monitor will be selected by default. Click the upper right monitor to select it as well. Both upper monitors should have a yellow border around them indicating they are selected.
6. Click on "Monitor Off" under the Source field to turn off the monitors off.
7. Click "Close" to close the module.

Turning On SuperTouch Consoles:

1. From the Conqueror X main menu, click on "Front Desk" then on "All Lanes."
2. Select which lanes you want to turn the monitors on by clicking and dragging.
3. Click on "Special F." on the bottom left of the screen.
4. Click on "TV".
5. The upper left monitor will be selected by default. Click on that monitor to de-select it.
6. Click on the lower left and lower right monitor. Both lower monitors should have a yellow border around them indicating they are selected.
7. Click in the drop down under "MMS Service" to select the advertising playlist or service you want to send to the lower monitors, then click "Send."
8. Click "Close" to close the module.

Turning Off SuperTouch Monitors:

1. From the Conqueror X main menu, click on "Front Desk" then on "All Lanes."
2. Select which lanes you want to turn the monitors on by clicking and dragging.
3. Click on "Special F." on the bottom left of the screen.
4. Click on "TV".
5. The upper left monitor will be selected by default. Click on that monitor to de-select it.
6. Click on the lower left and lower right monitor. Both lower monitors should have a yellow border around them indicating they are selected.
7. Click in the drop down under "MMS Service" and select the option "black screen," then click "Send."
8. Click "Close" to close the module.